



FLOOR SAFE LTD

COMPANY SPECIFIC RISK ASSESSMENT

Ref: Management of Health & Safety at Work Regulations 1999 (as amended)

ACTIVITY: **Slips/Trips/Falls on Clients Site**

DATE: May 2013

REVIEW DATE: May 2014

RISK RATING: **Low/Medium**

SIGNATURE:

HAZARD	WHO MIGHT BE HARMED?	IS THE RISK ADEQUATELY CONTROLLED?	WHAT FURTHER ACTION IS NECESSARY TO CONTROL THE RISK?
<ul style="list-style-type: none"> ➤ Electrical extension cables ➤ Carrying too big/heavy equipment. ➤ Poor lighting on site ➤ Wet/uneven floors on site includes application of Floor SAFE products ➤ Obstructions on floor ➤ Lack of staff safety awareness 	<ul style="list-style-type: none"> ➤ Staff ➤ Visitors ➤ Clients ➤ General public on clients sites 	<ul style="list-style-type: none"> ➤ Avoid any electrical cables crossing pedestrian routes ➤ Staff safety awareness at all times. ➤ Limit use of extension cables where possible ➤ Staff to wear safety footwear at all times ➤ Keep all walkways and fire exit routes clear on site ➤ Manual handling (HSE) guidance brochure INDG 143 and HSE guidance brochure Preventing Trips, Slips & falls INDG 225, available to staff ➤ Constant good floor housekeeping – No obstructions ➤ Immediate clear up of spills ➤ On site use of barriers tape & yellow folding "Men at Work" signs ➤ Written risk assessments including Manual Handling & Use of chemicals. ➤ First Aid kit & eye wash stations in vehicle ➤ PPE, High Viz vests, gloves and goggles all worn when required. ➤ All machinery & products are known weights and manual handling aids provided. 	<ul style="list-style-type: none"> ➤ Ongoing safety awareness